Example workshop

Technician: Example inspector

REPORT

Brakes and suspension - findings and measurements

10/26/2026

EXAMPLE

Ford Focus · 2019

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

Brake measurement 1

Position / axle	Front left
Measured disc thickness	24.1 mm
Measured pad thickness	4.2 mm
Notes	Illustrative readings; compare with vehicle specification.

Suspension component 1

CHECK	VALUE / NOTE	STATUS
Observed condition		Needs attention
Position / axle	Front right	
Component	Link	

Notes
Play observed during inspection; further assessment recommended.

Work and next steps

Work performed	Illustrative visual inspection and measurements.
Next steps	Further inspection and estimate before repair.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).