Example workshop

Technician: Example inspector

REPORT

Pre-ITP - preparatory inspection

26/10/2026

EXAMPLE

Dacia Logan · 2018

Date	Mileage	Customer
26/10/2026	**72,420 km**	**Example customer**

2 items need attention

We recommend addressing them soon.

12	2	0
OK	Needs attention	Critical

Summary

Inspector conclusion: Needs attention

Inspection basis

Country / inspection profile	Romania

Criteria used
Preparatory visual checks and measurements available in the workshop.

Criteria source / reference
Demonstration example; verify the applicable official criteria before actual use.

Inspection date	2026-10-26

Visibility and body

CHECK	VALUE / NOTE	STATUS
Windscreen		OK
Front window film		Not applicable
Observable structural corrosion		OK

Lighting and signals

CHECK	VALUE / NOTE	STATUS
Headlamp alignment		Needs attention
Number plate lights		OK
Reverse lights		OK
Fog lights		OK
Brake and turn lights		OK

Identity and documentation checks

CHECK	VALUE / NOTE	STATUS
VIN readability		OK
VIN accessibility		OK
VIN matches documents		OK
Engine identity readability		Not checked
Engine identity accessibility		Not checked
Engine identity, if applicable		Not checked
Tyre size matches vehicle identity document		OK

Preparatory technical checks

CHECK	VALUE / NOTE	STATUS
Emissions / engine warning lamps		OK
Exhaust leakage check		OK
Brake check		Not checked
Suspension check		Not checked

Preparatory findings

CHECK	VALUE / NOTE	STATUS
Preparatory check conclusion	Issues observed	Needs attention

Notes and recommended actions
The left headlamp requires alignment. Brake-roller testing and suspension inspection were not performed and are not declared satisfactory.

Unofficial preparatory check. This is not an official roadworthiness inspection, a certificate of conformity or a guarantee of passing an official inspection.

Inspector conclusion

Verdict: Needs attention

Preparatory inspection: correct the headlamp alignment before presenting the vehicle for the official Romanian inspection. A pass is not guaranteed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

26/10/2026, 09:10:00

Signed by: Example customer · Signed at: 26/10/2026, 09:10:00

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).